

## ASTM Flatness measurement standard. (ASTM A1030)

Flatness is the deviation of the surface of a sheet from a perfectly flat surface. Flatness is measured by placing a sheet on a horizontal flat surface with the prime side up and measuring the distance to the highest point of the sheet from the flat surface, then subtracting the material thickness.